



ASSEMBLY INSTRUCTION MONTAGEANLEITUNG



Installation of the tripod on the Handheld PC



Montage des Stativs am Handheld PC

Part no.


Artikel Nr. 924 001 217




MAL 924 007




Pos. 1	Tripod / Stativ	1 x
Pos. 2	USB-cable / USB-Kabel	1 x
Pos. 3	Washer / Unterlegscheibe DIN125-A3	1 x
Pos. 4	Cylinder screw / Zylinderschraube DIN7984-M3x8	1 x
Pos. 5	Cylinder screw / Zylinderschraube DIN7984-M4x8	2 x
Pos. 6	Countersunk screw / Senkschraube DIN7991-M4x30	2 x




Step: 2




Step: 1



Step: 3




Step: 4





**Step 5:
install**

Software AXIS4000



**Step 6:
connect**

USB-cable from Radio Server
USB-Kabel vom Sender

